

KİRİŞLERİN (bo) GENİŞLİĞİ (cm) VE (As) DONATISI (cm²)

TAŞIYICI ÇUBUK ÇAPI (mm)	3 ÇUBUK		4 ÇUBUK		5 ÇUBUK		6 ÇUBUK		7 ÇUBUK		8 ÇUBUK	
	bo	As	bo	As	bo	As	bo	As	bo	As	bo	As
12	11.8	3.4	15.0	4.5	18.2	5.7	21.4	6.8	24.6	7.9	27.8	9.1
14	12.4	4.6	15.8	6.2	19.2	7.7	22.6	9.2	26.0	10.8	29.4	12.3
16	13.0	6.0	16.6	8.0	20.2	10.0	23.8	12.1	27.4	14.1	31.0	16.1
18	14.0	7.6	17.8	10.2	21.2	12.7	25.4	15.3	29.2	17.8	33.0	20.4
20	14.6	9.4	18.6	12.6	22.6	15.7	26.6	18.8	30.6	22.0	34.6	25.1
22	15.6	11.4	20.0	15.2	24.4	19.0	28.8	22.8	33.2	26.6	37.6	30.4
24	16.6	13.6	21.4	18.1	26.2	22.6	31.0	27.1	35.8	31.7	40.6	36.2
26	17.6	15.9	22.8	21.2	28.0	26.5	33.2	31.9	38.4	37.2	43.6	42.5
28	19.0	18.5	24.6	24.6	30.2	30.8	35.8	36.9	41.4	43.1	47.0	49.3
30	20.0	21.2	26.0	28.3	32.0	35.3	38.0	42.4	44.0	49.5	50.0	56.5
32	21.0	24.1	27.4	32.2	33.8	40.2	40.2	48.3	46.6	56.3	53.0	64.3
34	22.4	27.2	29.2	36.3	36.0	45.4	42.8	54.5	49.6	63.6	56.4	72.6
36	23.4	30.5	30.6	40.7	37.6	50.9	45.0	61.1	52.2	71.3	59.4	81.4
38	24.8	34.0	32.4	45.4	40.0	56.7	47.6	68.0	55.2	79.4	62.8	90.7
40	25.8	37.7	33.8	50.3	41.8	62.8	49.8	75.4	57.8	88.0	65.8	100.0